



Harwich
Haven
Authority

www.hha.co.uk

2010

No. 18

NOTICE TO MARINERS

HARWICH APPROACHES

SUNK VESSEL TRAFFIC SERVICE

Mariners are advised that at 0001hrs on 19th July 2010 the following changes will be made to vessel traffic reporting points within the Sunk Inner Precautionary Area:

Walker Buoy Reporting Point- to be amended to 'out-bound' **only**.

A new reporting point is to be established 1.0' SE of the South Shipwash Buoy in position 51° 52.00'N 001°35.10'E for **Inbound Haven Ports Traffic Only**. This reporting point will be named **South Shipwash Reporting Point**.

All vessels must maintain a listening watch on VHF channels 71 and 14 whilst in transit between these two reporting points.

For full details of reporting points and further information see *Admiralty List of Radio Signals Volume 6(1)*.

30th June 2010

CAPTAIN C W BRAND
HARBOUR MASTER

LOCAL NOTICES CURRENTLY IN FORCE

2008 – 04; 2009 – 10,12,19; 2010 – 06,09,10,14,15,16,17,18

Harwich Haven Authority	Notice to Mariners	Ops 004
30.06.10	Sunk Vessel Traffic Service	18-2010